

NOTES:

- 1. DITCH SHALL HAVE LONGITUDINAL SLOPE OF 1%.
- 2. SILT FENCE MAY BE REQUIRED BEHIND BERM.

NOT TO SCALE



TEMPORARY SILT DITCH

SEPTEMBER 2022

208